



ASN CANADA FIA

2155 Leanne Blvd., Suite 115
Mississauga, Ontario Canada L5K 2K8
Telephone: (905) 403-9000
Fax: (905) 403-8448
E-mail: asncanada@rogers.com

Canadian Karting Regulations BULLETIN 09-04 Book 2 Technical Regulations

SUBJECT: HONDA FOUR-CYCLE INSPECTION PROCEDURES

EFFECTIVE DATE: April 20, 2009

28.7. Camshaft Inspection

Delete 28.7. b) and replace with the following:

b) Checking Rocker Arm Ratio:

Actual valve lift at the retainer with zero lash may be determined using the appropriate tool. **All dimensional measurements of any parts in the valve train apparatus must conform to appropriate and comparable OEM standards and measurements. Maximum actual intake valve movement allowed is 0.248".**

Pending a final determination, the maximum actual exhaust valve movement allowed is 0.256".